

Informativa tecnica / Technical notice

HONDA

CRF1100L Africa Twin / Adventure Sports

VEHICLE TYPE: SD09

EC
ECE

CARB

COLLETTORI RACING IN TITANIO
TITANIUM RACING COLLECTORS
72168PD *

COLLETTORI RACING IN ACCIAIO
STEEL RACING COLLECTORS
72166PD *

7

7

| ECE | | HOMOL. |
|------------------|-------------------|--------|
| TITANIUM | 72625PK * | |
| ALUMINIUM | 72625AK * | |
| ALUMINIUM "DARK" | 72625AKN * | |

| ECE | | HOMOL. |
|------------------|-------------------|--------|
| TITANIUM | 72625PO * | |
| ALUMINIUM | 72625AO * | |
| ALUMINIUM "DARK" | 72625AON * | |

*** TUTTI I COMPONENTI SONO INTERCAMBIABILI CON QUELLI ORIGINALI**
ALL THE COMPONENTS ARE INTERCHANGEABLE WITH THE ORIGINAL ONES

| Italiano | English |
|--|---|
| <p>Lo scarico originale Honda è dotato di valvola allo scarico, montata sul silenziatore originale. L'installazione di uno dei silenziatori Arrow realizzati per CRF1100L richiede la rimozione della valvola allo scarico. Il sistema di diagnostica di bordo (EOBD) segnala il mancato funzionamento della valvola mediante un segnale di errore sul display e la centralina può entrare in modalità "protezione".</p> <p>Installando quindi uno dei silenziatori Arrow è fortemente consigliata la rimappatura mediante una mappa centralina che escluda la funzione valvola o, in alternativa, l'installazione di un emulatore valvola elettronico tra quelli disponibili sul mercato.</p> | <p>Honda original equipment exhaust system fits an exhaust valve, placed on OE silencer. Installing any Arrow silencers available for CRF1100L requires the removal of the exhaust valve. On-board diagnostic system (EOBD) will display a warning message due to the exhaust valve malfunction and ECU can enter "recovery mode".</p> <p>Therefore, when installing any Arrow silencers it is strongly recommended to remap ECU with a map deactivating exhaust valve function or, as an alternative, to install an exhaust valve emulator system, available in the market</p> |